

VEHICLE INSPECTION REPORT

HT69YLJ

Skoda Kodiaq 2.0 TDI SE

Inspection

Serious Damage? No

Vehicle

VAT	VAT Qualifying
V5	Present
Cap Id	77504
Cap Code	SKKO207SE5EDTM4

nama

GRADE
1

Details

Location	Bedford	Colour	SILVER	CAP Below	£10,500.00
Reg. date	10/02/2020	VIN	TMBMJ7NS6L8509081	Gearbox	MANUAL
Year	2020	Body Style	Estate	Gears	6
Mileage	43,262 Miles Warranted	MOT Due	23/11/2026	Doors	5
Fuel Type	DIESEL	CAP Clean	£12,900.00	Axle Combi	4x4
GVW	2443kg	CAP Average	£11,700.00		

EX-FIRE SERVICE CONTRACT - BLUE LIGHTS REMOVED E/MIRRORS, KEYLESS IGNITION, AD BLUE

Tyres

NSF

NSR

OSF

OSR

Spare





Features

- Rear parking sensor
- Body coloured bumpers
- Air conditioning
- Front electric windows
- Leather seat trim
- Alloy wheels


Photos







Condition Check



Damage Photos



1: Qtr Panel osr
Dented
Over 2 UpTo 10mm

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	No

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK