

VEHICLE INSPECTION REPORT

FD680FB

Daf CF 450

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Location	Doncaster	GVW	32000kg	MOT Due	28/02/2027
Reg. date	18/02/2019	Colour	WHITE	Cab Type	SLEEPER CAB
Year	2019	VIN	XLADM4100G245125	Gearbox	AUTOMATIC
Mileage	529,110 Km Warranted	Body Style	Tipper	Axle Combi	8x4
Fuel Type	DIESEL	Service history	None	Rear Suspension	Steel

WARNING LIGHT ON DASH, BULKRITE ALLOY BODY, EDBRO TIPPING GEAR, SHEETING SYSTEM, WEIGH SYSTEM

Tyres




NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Bluetooth connection
- Digital radio
- Central locking
- Cruise control
- Radio/CD
- Cloth seat trim
- Navigation system
- Air conditioning
- Park assist camera
- Front electric windows


Photos







Condition Check



Damage Photos



1: Door osf
Scratched
Over 25mm Thru Paint

2: Door osf
Scratched
Over 25mm Not Thru Paint




3: Bumper Front
Scratched
Over 100mm Thru Paint

4: Bonnet
Chipped
Multiple Chips



5: Bumper Front
Chipped
Multiple Chips

6: Bumper Front
Scratched
Over 100mm Thru Paint



7: Wing nsf
Scratched
Over 25mm Thru Paint

8: Qtr Panel osr
Dented
Over 30mm

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	Fault	DPF light illuminated	OK
ABS light illuminated	OK		