

VEHICLE INSPECTION REPORT

RV22DVJ

Iveco Daily 72-180

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Location	Avonmouth	GVW	7200kg	Cab Type	DAY CAB
Reg. date	05/04/2022	Colour	BLACK	Gearbox	AUTOMATIC
Year	2022	VIN	ZCFC670D605313525	Axle Combi	4x2
Mileage	147,786 Km Warranted	Body Style	Box Van	Rear Suspension	Steel
Fuel Type	DIESEL	MOT Due	31/08/2027	Tail Lift	Cantilever



Tyres


NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features


- Bluetooth connection
- Cruise control
- Radio/CD
- Air conditioning
- Front electric windows
- Drivers airbag
- Central locking
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips

2: Bonnet
Dented
With Paint Damage



3: Bumper Front Moulding
Missing
Replace

4: Door nsf
Scratched
Over 25mm Thru Paint



5: Door nsf
Chipped
Multiple Chips

6: Qtr Panel nsr
Chipped
Multiple Chips



7: Qtr Panel nsr
Chipped
Multiple Chips

8: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



9: Panel Rear
Scratched
Over 25mm Thru Paint

10: Qtr Panel osr
Chipped
Multiple Chips



11: Qtr Panel osr
Dented
Over 30mm

12: Qtr Panel osr
Cracked
Replace



13: Door osf
Chipped
Multiple Chips

14: Door osf
Chipped
Multiple Chips



15: Bumper Front Moulding
Missing
Replace

16: Carpets Front
Broken
Replace

Interior

Carpet Condition		Upholstery Condition	
Seat Condition		Odour	
Poor		Average	
Average		-	
Engine Runs	OK	No Excessive Smoking	OK
Brakes	OK		
Parking Brake	OK		
EML light illuminated	OK	DPF light illuminated	OK
Airbag light illuminated	OK		
ABS light illuminated	OK		