

VEHICLE INSPECTION REPORT

RE710VJ

Iveco Daily 72-180

Inspection

Vehicle

VAT	Plus VAT
V5	Present

Details

Location	Avonmouth	GVW	7200kg	Cab Type	SLEEPER CAB
Reg. date	24/01/2022	Colour	SILVER	Gearbox	AUTOMATIC
Year	2022	VIN	ZCFC670D905314135	Axle Combi	4x2
Mileage	154,549 Km Warranted	Body Style	Box Van	Rear Suspension	Steel
Fuel Type	DIESEL	MOT Due	31/01/2027	Tail Lift	Cantilever

Tyres







NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4


Features

- Bluetooth connection
- Cruise control
- Digital radio
- Air conditioning
- Front electric windows
- Drivers airbag
- Central locking
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips

2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Bumper Front Moulding
Missing
Replace

4: Wing nsf
Scratched
Over 25mm Thru Paint



5: Door nsf
Dented
With Paint Damage

6: Door nsf
Chipped
Multiple Chips



7: Qtr Panel nsr
Scratched
Over 25mm Thru Paint

8: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



9: Qtr Panel osr
Scratched
Over 25mm Thru Paint

10: Door osf
Chipped
Multiple Chips



11: Bumper Front Moulding
Missing
Replace

12: Bumper Front
Scratched
Over 100mm Thru Paint



13: Fascia Trim
Damaged
Replace

14: Carpets Front
Broken
Replace

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
Brakes	OK		
Parking Brake	OK		
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		