

VEHICLE INSPECTION REPORT

C337691

MONTRACON FRIDGE BOX

Inspection

Serious Damage?	No	VAT	Plus VAT
		V5	N/A

Details


Reg. date	01/01/2011	Colour	White	Axle Combi	Tri
Year	2011	VIN	N102207	Rear Suspension	Air
Mileage	26,014 Hours Not Warranted	Body Style	Trailer	Rear Doors	Barn
Fuel Type		Brakes	Drum		

BPW AXLES, CARRIER VECTOR 1850MT UNIT, TWIN EVAPS, PARTITION DOOR, 26014 ENGINE HOURS, 67224 SWITCH HOURS, 67224 RUN HOURS, NEW ALLOY RIMS, RAISE & LOWER VALVE, FERRY LASHING RINGS

Tyres

NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Condition Check



Damage Photos

Interior

Carpet Condition	-	Upholstery Condition	-
Seat Condition	-	Odour	-