

VEHICLE INSPECTION REPORT

NX68UFD

Man TGS 35.420

Non Runner

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Cap Code 999900

Details

Location Doncaster

Reg. date 18/09/2018

Year 2018

Mileage 384,517 Km Not Warranted

Fuel Type Diesel

Colour WHITE

VIN WMA37SZZ3KM801980

Body Style Tipper

Gearbox Automatic

STARTS BUT OVER REVS & SMOKES HEAVILY, OIL COMING FROM EXHAUST, TIPPER BODY FULL OF AGGREGATE WASTE BINOTTO TIPPING GEAR

Tyres

NSF NSI1

NSI2

NSI3

NSI4

OSF OSI1

OSI2

OSI3

OSI4

Spare NSO1

NSO2

NSO3

NSO4

OSO1

OSO2


OSO3

OSO4

Features

- Bluetooth connection
- Cruise control
- Park assist camera
- Digital radio
- Air conditioning
- Front electric windows
- Central locking
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Bumper Front
Dented
With Paint Damage



4: Door Mirror Assy nsf
Broken
Replace



5: Panel Front
Scratched
Over 25mm Thru Paint



6: Qtr Panel Moulding ns
Broken
Replace



7: Other
N/A
N/A



8: Other
N/A
N/A



9: Qtr Panel osr
Chipped
Multiple Chips



10: Screen Front
Chipped
Over 10mm



11: Seat Base Cover nsf
Soiled
Heavy

Interior

Carpet Condition
Seat Condition

OK
Poor

Upholstery Condition
Odour

OK
-

Engine Runs **Fault**