

VEHICLE INSPECTION REPORT

SJ67LFL

Iveco Daily 35-140 HIMATIC

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Location	Livingston	Colour	WHITE	CAP Below	£5,075.00
Reg. date	03/10/2017	VIN	ZCFCD35A505175974	Gearbox	Automatic
Year	2017	Body Style	Tipper Double Cab	Gears	6
Mileage	80,391 Miles Warranted	MOT Due	14/03/2027	Tail Lift	Column
Fuel Type	DIESEL	CAP Clean	£8,200.00		
GVW	3500kg	CAP Average	£6,850.00		

TOW BAR, LEATHER, REAR VIEW CAMERA.

Tyres

NSF

NSR

OSF


OSR



Spare

Features


- Radio/CD
- Front electric windows
- Central locking

Photos





Condition Check



Damage Photos



1: Seat Base Cover osf
Torn
Over 3mm



2: Roof
Rusted
Over 5mm



3: Bonnet
Dented
With Paint Damage

4: Bumper Front
Cracked
Over 25mm



5: Wing osf
Dented
With Paint Damage

6: Door osf
Dented
With Paint Damage



7: Door osr
Dented
With Paint Damage

8: Qtr Panel osr
Dented
With Paint Damage





9: Tailgate
Dented
With Paint Damage

10: Qtr Panel nsr
Dented
With Paint Damage



11: Door nsr
Dented
With Paint Damage

12: Door nsf
Dented
With Paint Damage

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK

Windows

OK

Radio

OK

Steering

OK