

VEHICLE INSPECTION REPORT

C377926

MONTRACON CURTAINSIDE

Inspection

Vehicle

VAT	Plus VAT
V5	N/A

Details

Location	Doncaster Trailer Centre	Fuel Type		MOT Due	31/08/2027
Reg. date	01/01/2014	Colour	BLUE	Axle Combi	Tri
Year	2014	VIN	SMRC3AXXXEN112519	Rear Suspension	Air
Mileage	Not Showing	Body Style	Trailer	Rear Doors	Barn

SAF AXLES, RAISE & LOWER VALVE

Tyres

NSF
NSR
OSF
OSR
Spare

Photos





