

VEHICLE INSPECTION REPORT

HX73YSK

Mercedes-Benz Atego 816

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Present

Details					
Location	Bedford	GVW	7490kg	Cab Type	DAY CAB
Reg. date	26/02/2024	Colour	WHITE	Gearbox	AUTOMATIC
Year	2024	VIN	W1T96700120676850	Axle Combi	4x2
Mileage	7,601 Km Warranted	Body Style	POLE CARRYING UNIT	Rear Suspension	Steel
Fuel Type	DIESEL	MOT Due	28/02/2027		


WARNING LIGHT ON DASH HIAB X-HIDOU 062 REMOTE CRANE (YEAR 2023)


Tyres				
NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Air conditioning


Photos







Condition Check



Damage Photos

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	-
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	Fault