

VEHICLE INSPECTION REPORT

HX73YRF

Mercedes-Benz Atego 816

Inspection

Serious Damage?	No	VAT	Plus VAT
		V5	Present

Vehicle

Details

Location	Doncaster	GVW	7490kg	Service documents	Printout
Reg. date	23/01/2024	Colour	WHITE	Cab Type	DAY CAB
Year	2024	VIN	W1T96700320669866	Gearbox	AUTOMATIC
Mileage	4,202 Km Warranted	Body Style	POLE CARRIER	Axle Combi	4x2
Fuel Type	DIESEL	Service history	Yes	Rear Suspension	Steel

CRANE REMOTE INOP X-HIDUO 062 B-2 (YEAR 2023)


Tyres



NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4


Features

- Bluetooth connection
- Air conditioning
- Cruise control
- Front electric windows
- Park assist camera
- Central locking
- Digital radio
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm



2: Door Mirror Assy nsf
Broken
Replace



3: Wing osf
 Scratched
 Over 25mm Thru Paint

4: Screen Front
 Chipped
 Over 10mm

Interior

Carpet Condition		OK	Upholstery Condition		OK
Seat Condition		OK	Odour		-
Engine Runs		OK	No Excessive Smoking		OK
EML light illuminated		OK	DPF light illuminated		OK
ABS light illuminated		OK			