

VEHICLE INSPECTION REPORT

HX24WRN

Mercedes-Benz Atego 816

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Location	Doncaster	GVW	7490kg	Service documents	Printout
Reg. date	08/05/2024	Colour	WHITE	Cab Type	DAY CAB
Year	2024	VIN	W1T96700220678882	Gearbox	AUTOMATIC
Mileage	1,366 Km Warranted	Body Style	POLE CARRIER	Axle Combi	4x2
Fuel Type	DIESEL	Service history	Yes	Rear Suspension	Steel

WARNING LIGHTS ON DASH X-HIDUO 062 B-2 REMOTE CRANE (YEAR 2023)

Tyres



NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4



Features

- Bluetooth connection
- Digital radio
- Cloth seat trim
- Cruise control
- Air conditioning
- Park assist camera
- Front electric windows
- Auxiliary input socket
- Central locking


Photos







Condition Check



Damage Photos



1: Door Mirror Assy nsf
Scuffed (Unpainted)
UpTo 100mm

2: Dash Warning Lights
Displayed
No Action

Interior

Carpets Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	-
Engine Runs	OK	No Excessive Smoking	OK

EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	Fault