

VEHICLE INSPECTION REPORT

NL25WYV

Mercedes-Benz Sprinter 315 CDI

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Details

Location	Doncaster	GVW	3500kg	CAP Average	£22,250.00
Reg. date	12/05/2025	Colour	WHITE	CAP Below	£20,000.00
Year	2025	VIN	W1V3HCFZ7SP739530	Gearbox	MANUAL
Mileage	62,259 Miles Not Warranted	Body Style	Panel Van L3	Gears	6
Fuel Type	DIESEL	CAP Clean	£23,150.00		

AD-BLUE, SIDE LOAD DOOR, E/ MIRRORS

Tyres

NSF

NSR

OSF


OSR





Spare

Features

- Bluetooth connection
- Drivers airbag
- Cruise control
- Passenger airbag
- Digital radio
- Central locking
- Front electric windows
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips

2: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



3: Door nsr
 Scratched
 Over 25mm Thru Paint

4: Door nsr
 Scratched
 UpTo 25mm Thru Paint



5: Door osr
 Scratched
 Over 25mm Thru Paint

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	No
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		