

VEHICLE INSPECTION REPORT

BK68RZV

Skoda Kodiaq 2.0 TDI SE TECH

Inspection

Serious Damage? No

Vehicle

VAT	VAT Qualifying
V5	Present
Cap Id	77952
Cap Code	SKKO20STE5EDTA4

Details

Location	Doncaster	Colour	RED	CAP Below	£9,500.00
Reg. date	20/12/2018	VIN	TMBMJ7NS6K8028178	Gearbox	AUTOMATIC
Year	2018	Body Style	Estate	Gears	7
Mileage	61,097 Miles Warranted	MOT Due	19/12/2026	Doors	5
Fuel Type	DIESEL	CAP Clean	£11,950.00	Axle Combi	4x4
GVW	2387kg	CAP Average	£10,750.00		

EX-FIRE SERVICE CONTRACT - BLUE LIGHTS REMOVED KEYLESS IGNITION, DUAL ZONE CLIMATE CONTROL

Tyres


NSF
NSR
OSF
OSR
Spare


Features

- Bluetooth connection
- Navigation system
- Steering wheel mounted controls
- Front electric windows
- Passenger airbag
- Cruise control
- PAS
- Trip computer
- Rear electric windows
- Central locking
- Front parking sensor
- Rear parking sensor
- Digital radio
- Metallic Paint
- Cloth seat trim
- Heated front seat
- Rear wiper
- Air conditioning
- Drivers airbag
- Alloy wheels


Photos







Condition Check



Damage Photos



1: Bumper Front Moulding
Scuffed (Unpainted)
UpTo 100mm

2: Bumper Front
Chipped
Multiple Chips



3: Bonnet
Chipped
Multiple Chips

4: Wing nsf
Scratched
Over 25mm Thru Paint



5: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Thru Paint

6: Door nsf
Chipped
Multiple Chips



7: Door nsr
Scratched
Over 25mm Thru Paint

8: Qtr Panel osr
Chipped
Multiple Chips



9: Door osr
Dented
With Paint Damage

10: Wing osf
Scratched
Over 25mm Thru Paint

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	No
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		