

VEHICLE INSPECTION REPORT

SK22UYL

Ford Transit Custom 300 2.0 EcoBlue 170ps Limited model

Non Runner
Inspection

Serious Damage?	No	Vehicle	
		VAT	Plus VAT
		V5	Buyer To Apply

Details

Location	Avonmouth	GVW	3000kg	CAP Clean	£12,400.00
Reg. date	25/05/2022	Colour	BLUE	CAP Average	£11,250.00
Year	2022	VIN	WF0YXXTTGYNS57486	CAP Below	£9,450.00
Mileage	62,313 Miles Not Warranted	Body Style	Panel Van L2	Gearbox	MANUAL
Fuel Type	DIESEL	MOT Due	Expired	Gears	6

NON-RUNNER-TURNS OVER, DOES NOT START, WET BELT ISSUES, AD BLUE, SIDE LOAD DOOR, ROOF RACK, E/MIRRORS, HEATED WINDSCREEN

Tyres

NSF

NSR

OSF

OSR







Spare

Features


- Bluetooth connection
- Park assist camera
- Air conditioning
- Central locking
- Cruise control
- Rear parking sensor
- Front electric windows
- Leather seat trim
- Front parking sensor
- Radio/CD
- Drivers airbag
- Heated front seat
- USB/iPod interface
- Passenger airbag

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips

2: Bumper Front
Scratched
25 to 100mm Thru Paint




3: Bumper Front
Cracked
Over 25mm

4: Wing nsf
Dented
Hail - Severe



5: Door nsf
Scratched
Over 25mm Thru Paint

6: Door nsf
Chipped
Multiple Chips



7: Sill Panel Trim ns
Missing
Replace

8: Qtr Panel nsr
Dented
With Paint Damage



9: Aperture Seal nsr
Broken
Replace

10: Qtr Panel nsr
Dented
Hail - Severe



11: Door nsr
Scratched
Over 25mm Thru Paint

12: Door osr
Scratched
Over 25mm Thru Paint



13: Qtr Panel osr
Scratched
Over 25mm Thru Paint

14: Qtr Panel osr
Dented
With Paint Damage



15: Qtr Panel osr
Scratched
Over 25mm Thru Paint

16: Qtr Panel Trim os
Broken
Replace



17: Door osf
Chipped
Multiple Chips

18: Wheel osf
Damaged
Replace



19: Door Mirror Assy osf
Scratched (Painted)
Over 25mm Thru Paint

20: Bumper Front
Scratched
Over 100mm Thru Paint



21: Bumper Front
Scratched
Over 100mm Thru Paint

22: General Interior
Soiled
Light



23: Fascia Trim
Damaged
Replace

Interior

Carpet Condition	Poor	Upholstery Condition	Poor
Seat Condition	Poor	Odour	-
Engine Runs		Fault	