

VEHICLE INSPECTION REPORT

C255149

SDC CURTAINSIDE

Inspection

Vehicle

VAT	Plus VAT
V5	N/A

Details

Location	Avonmouth	Colour	BLUE	Axle Combi	Tri
Reg. date	01/01/2008	VIN	SDCPL45R3AAA76665	Rear Suspension	Air
Year	2008	Body Style	Trailer	Rear Doors	Barn
Mileage	Not Showing	MOT Due	31/10/2026		
Fuel Type		Brakes	Drum		

ROR AXLES, FERRY LASHING RINGS

Tyres

NSF
NSR
OSF
OSR
Spare

Photos



