

VEHICLE INSPECTION REPORT

YX70NDD

Daf XF 480

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Details

Reg. date 18/09/2020

Year 2020

Mileage 681,437 Km Not Warranted

Fuel Type DIESEL

GVW 44000kg

Colour WHITE

VIN XLRTGH4300G293813

Body Style Tractor Unit

MOT Due 30/09/2026

Cab Type SUPER SPACE CAB

Gearbox AUTOMATIC

Axle Combi 6x2

Steering Combi Mid-Lift

Rear Suspension Air

WARNING LIGHTS ON DASH, SLIDING 5TH WHEEL

Tyres




NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4




Features

- Bluetooth connection
- Air conditioning
- Cruise control
- Front electric windows
- Radio/CD Multichanger
- Central locking
- Electric sunroof
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips

2: Bumper Front
Chipped
Multiple Chips




3: Wing nsf
Cracked
Replace

4: Door nsf
Scratched
Over 25mm Thru Paint



5: Door nsf
Scratched
Over 25mm Thru Paint

6: Wing Front Arch Extension ns
Broken
Replace



7: Qtr Panel nsr
Scratched
Over 25mm Thru Paint

8: Qtr Panel nsr
Hole
Over 10mm



9: Panel Rear
Cracked
Replace

10: Door osf
Chipped
Multiple Chips



11: Door osf
Scratched
Over 25mm Thru Paint

12: Door osf
Scratched
Over 25mm Thru Paint



13: Bumper Front
Chipped
Multiple Chips

14: Carpets Front
Holed
Over 3mm



15: Dash Warning Lights
Displayed
No Action

Interior

Carpet Condition		Average	Upholstery Condition		Average
Seat Condition		Average	Odour		-
Engine Runs		OK	No Excessive Smoking		OK
Brakes		OK			
Parking Brake		OK			
EML light illuminated		Fault	DPF light illuminated		Fault
ABS light illuminated		Fault			