

VEHICLE INSPECTION REPORT

YX70NDO

Daf XF 480

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Details

Reg. date 18/09/2020

Year 2020

Mileage 643,394 Km Not Warranted

Fuel Type DIESEL

GVW 44000kg

Colour WHITE

VIN XLRTGH4300G291842

Body Style Tractor Unit

MOT Due 30/09/2026

Cab Type SUPER SPACE CAB

Gearbox AUTOMATIC

Axle Combi 6x2

Steering Combi Mid-Lift

Rear Suspension Air

WARNING LIGHTS ON DASH, SLIDING 5TH WHEEL

Tyres

NSF NSI1

NSI2

NSI3

NSI4

OSF OSI1

OSI2

OSI3

OSI4

Spare NSO1

NSO2

NSO3

NSO4

OSO1

OSO2

OSO3





OSO4


Features

- Bluetooth connection
- Air conditioning
- Cruise control
- Front electric windows
- Radio/CD
- Central locking
- Electric sunroof
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Dash Warning Lights
Displayed
No Action

2: Bonnet
Chipped
Multiple Chips



3: Bumper Front
Chipped
Multiple Chips

4: Moulding nsf Wing
Scratched (Painted)
Over 25mm Thru Paint



5: Panel Rear
Cracked
Replace

6: Qtr Panel nsr
Hole
UpTo 10mm



7: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm

8: Panel Rear
Cracked
Replace



9: Qtr Panel osr
Scratched
Rusted

10: Qtr Panel osr
Chipped
Multiple Chips



11: Door osf
Chipped
Multiple Chips

12: Moulding osf Wing
Broken
Replace

Interior

Carpet Condition		Average	Upholstery Condition		Average
Seat Condition		Average	Odour		-
Engine Runs		OK	No Excessive Smoking		OK
Brakes		OK			
Parking Brake		OK			
EML light illuminated		Fault	DPF light illuminated		OK
ABS light illuminated		OK			