

VEHICLE INSPECTION REPORT

WV52GZZ

Man L 2000

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Location	Avonmouth	GVW	12000kg	Cab Type	DAY CAB
Reg. date	17/11/2002	Colour	WHITE/BLUE	Gearbox	MANUAL
Year	2002	VIN	WMAL70ZZZ3Y108560	Axle Combi	4x2
Mileage	100,248 Km Warranted	Body Style	Dropside & Crane	Rear Suspension	Steel
Fuel Type	DIESEL	MOT Due	31/10/2026		

PK6500 (YEAR 2002)

Tyres





NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features


- Radio/CD
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips

2: Bonnet
Dented
With Paint Damage




3: Moulding nsf Wing
Broken
Replace

4: Wing nsf
Dented
With Paint Damage



5: A Post ns
Rusted
Over 5mm

6: Wing nsf
Cracked
Replace



7: Door nsf
Chipped
Multiple Chips

8: Qtr Panel nsr
Chipped
Multiple Chips



9: Panel Rear
Rusted
Over 5mm



10: Qtr Panel osr
Rusted
Over 5mm



11: Qtr Panel osr
Scratched
Over 25mm Thru Paint

12: Door osf
Chipped
Multiple Chips



13: Fascia Trim
Missing
Replace

14: Fascia Trim
Damaged
Replace



15: Seat Base Cover nsf
Holed
UpTo 3mm

16: Fascia Panel
Missing
Replace



17: Fascia Trim
Damaged
Replace

18: Fascia Trim
Missing
Replace



19: Centre Console Front
Holed
Over 3mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	-
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		