

VEHICLE INSPECTION REPORT

LT68GBZ

Mercedes-Benz Arocs 3240

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Details

Reg. date	08/11/2018	Colour	WHITE	Cab Type	DAY CAB
Year	2018	VIN	WDB96423020237406	Gearbox	AUTOMATIC
Mileage	206,833 Km Warranted	Body Style	Tipper Grab	Axle Combi	8x4
Fuel Type	DIESEL	MOT Due	30/11/2025		

COLLECTED AS NON RUNNER - BEEN STOOD A WHILE PALFINGER EPSILON M125L CRANE (YEAR UNKNOWN), SHEETING SYSTEM

Tyres




NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Bluetooth connection
- Air conditioning
- Cruise control
- Front electric windows
- Park assist camera
- Central locking
- Radio/CD
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Bumper Front
Poor Previous Repair
Poor Paint



2: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



3: Wing Front Arch Extension ns
Scuffed (Unpainted)
Over 100mm

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		