

VEHICLE INSPECTION REPORT

2266

TORO 74534TE

Inspection

Vehicle

VAT	Plus VAT
V5	N/A

Details

Location	Bedford	Mileage	1,348 Hours Not Warranted	VIN	405499674
Reg. date		Fuel Type		Body Style	MOWER
Year	2019	Colour			

NON RUNNER-NO KEYS

Tyres

NSF
NSR
OSF
OSR
Spare

Photos



