

VEHICLE INSPECTION REPORT

YD16FBY

Scania R 580

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Location Avonmouth

Reg. date 09/03/2016

Year 2016

Mileage 1,060,053 Km Not Warranted

Fuel Type DIESEL

GVW 44000kg

Colour WHITE

VIN YS2R6X20005415036

Body Style Tractor Unit

MOT Due Expired

Cab Type TOPLINE CAB

Gearbox AUTOMATIC

Axle Combi 6x2

Rear Suspension Air

WARNING LIGHTS ON DASH, TWIN FUEL TANKS, SLIDING 5TH WHEEL, REAR-LIFT

Tyres







NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Bluetooth connection
- Cruise control
- Front electric windows
- Central locking
- Leather seat trim


Photos








Condition Check



Damage Photos



1: Dash Warning Lights
Displayed
No Action



2: Switches And Controls
Missing
Replace




3: In Car Entertainment
Broken
Replace

4: Fascia Trim
Damaged
Replace



5: In Car Entertainment
Broken
Replace

6: In Car Entertainment
Broken
Replace



7: Fascia Trim
Damaged
Replace

8: Fascia Trim
Damaged
Replace



9: Screen Front
Cracked
Replace

10: Bumper Front Grill
Broken
Replace



11: Fogdriving Lamp nsf
Broken
Replace

12: Bumper Front
Cracked
Over 25mm



13: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm

14: Wing Front Arch Extension ns
Missing
Replace



15: Wing Front Arch Extension os
Missing
Replace

16: Qtr Panel osr
Cracked
Replace



17: Qtr Panel osr
Poor Previous Repair
Paint Flake

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
Brakes	OK		
Parking Brake	OK		
EML light illuminated	Fault	DPF light illuminated	Fault
ABS light illuminated	OK		