

VEHICLE INSPECTION REPORT

FN19KCA

Daf XF 480

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 10/03/2019

Year 2019

Mileage 642,343 Km Not Warranted

Fuel Type Diesel

Colour WHITE

VIN XLRTGH4300G247683

Body Style Tractor Unit

MOT Due 31/01/2026

Cab Type SUPER SPACE CAB

Gearbox AUTOMATIC

Axle Combi 6x2

Steering Combi Mid-Lif Steert

Rear Suspension Air

*WARNING LIGHT ON DASH**SLIDING 5TH WHEEL COUPLING MISSING*SLIDING 5TH WHEEL

Tyres

NSF NSI1

NSI2

NSI3

NSI4

OSF OSI1

OSI2

OSI3

OSI4

Spare NSO1

NSO2

NSO3

NSO4

OSO1

OSO2

OSO3



OSO4



Features

- Bluetooth connection
- Radio/CD
- Cloth seat trim
- Cruise control
- Air conditioning
- Navigation system
- Front electric windows
- Park assist camera
- Central locking


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Chipped
Multiple Chips



3: Qtr Panel nsr
 Scratched
 Over 25mm Not Thru Paint



4: Wing nsf
 Chipped
 Multiple Chips



5: Qtr Panel Trim os
 Broken
 Replace



6: Dash Warning Lights
 Displayed
 No Action

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	Fault	DPF light illuminated	OK
ABS light illuminated	OK		