

VEHICLE INSPECTION REPORT

FJ18YKA

Vauxhall Vivaro 2900 1.6 CDTI 95PS

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Present
		Cap Id	38225
		Cap Code	VAVI16L129VDTM2 2 L

Details

Location	Avonmouth	Colour	WHITE	CAP Average	£3,475.00
Reg. date	09/03/2018	VIN	W0VF7F60XJV627010	CAP Below	£2,650.00
Year	2018	Body Style	Panel Van L1	Gearbox	MANUAL
Mileage	102,168 Miles Warranted	Service history	Yes	Gears	6
Fuel Type	DIESEL	MOT Due	08/03/2027		
GVW	2960kg	CAP Clean	£4,125.00		

AD BLUE, TWIN SIDE LOAD DOOR, ROOF RACK, E/MIRRORS

Tyres

NSF

NSR

OSF

OSR


Spare

Features

- Bluetooth connection
- Front electric windows
- Cloth seat trim
- Rear parking sensor
- Drivers airbag
- Auxiliary input socket
- Passenger airbag
- USB/iPod interface
- Central locking


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Dented
Over 30mm



3: Bumper Front
Insecure
Action Required



4: Flasher Side Repeater ns
Missing
Replace



5: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm



6: B Post ns
Dented
Over 30mm



7: Door nsr
Chipped
Edge Chip



8: Door nsr
Chipped
Multiple Chips



9: Qtr Panel nsr
Chipped
Over 5mm



10: Door nsr
Rusted
Over 5mm



11: Door nsr
Dented
Over 30mm



12: Door osr
Chipped
Multiple Chips




13: Bumper Rear
Dented
Over 30mm



14: Door nsr
Chipped
Edge Chip



15: Door osr
Chipped
Over 5mm



16: Door osr
Scratched
Over 25mm Thru Paint



17: Door osf
Chipped
Over 5mm



18: Door osf
Chipped
Edge Chip



19: Wing osf
Chipped
Over 5mm



20: A Post os
Chipped
Multiple Chips



21: Bumper Front
Scratched
Over 25mm Not Thru Paint



22: Seat Base Cover osf
Torn
Over 3mm



23: Centre Console Front
Holed
Over 3mm



24: Carpets Front
Holed
Over 3mm

Interior

Carpet Condition		Average		Upholstery Condition		Average	
Seat Condition		Average		Odour		-	
Engine Runs	OK			Gearbox 1st and Reverse Test	OK		
Brakes	OK			Clutch Slip Test from Static	OK		
Parking Brake	OK			Gearbox Static Gear Selection (engine running)	OK		
				No Excessive Smoking	OK		
EML light illuminated	OK			Oil warning light illuminated	OK		
Airbag light illuminated	OK			DPF light illuminated	OK		
ABS light illuminated	OK			Service indicator light illuminated	OK		
				Radio	OK		

