

VEHICLE INSPECTION REPORT

HX74WYF

Mercedes-Benz Atego

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Location Doncaster

Mileage 146 Km Warranted

VIN W1T96700120761249

Reg. date 16/01/2025

Fuel Type DIESEL

Body Style Flat Lorry

Year 2025

Colour WHITE

Service history Yes

WARNING LIGHT ON DASH, X-HIDUO 062 B-2 (YEAR 2023)



Tyres



NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Bluetooth connection
- Digital radio
- Cloth seat trim
- Cruise control
- Air conditioning
- Park assist camera
- Front electric windows
- Auxiliary input socket
- Central locking


Photos







Condition Check



Damage Photos



1: Door Mirror Assy nsf
Scuffed (Unpainted)
UpTo 100mm



2: Dash Warning Lights
Displayed
No Action



3: Dash Warning Lights
Displayed
No Action

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	Fault	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	Fault