

VEHICLE INSPECTION REPORT

HX24WRL

Mercedes-Benz Atego 816

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Cap Code 999900

Details

Location Doncaster

Reg. date 17/04/2024

Year 2024

Mileage 544 Km Warranted

Fuel Type DIESEL

GVW 7490kg

Colour WHITE

VIN W1T96700720675928

Body Style Flatbed & Crane

Service history Full

Service documents Printout

Last service date 16/05/2026

Cab Type DAY CAB

Gearbox AUTOMATIC

Axle Combi 4x2

Rear Suspension Steel

WARNING LIGHT ON DASH HIAB X HIDUO 062 B 2 (EXT) REMOTE CRANE (YEAR 2023)

Tyres

NSF NSI1

NSI2

NSI3

NSI4

OSF OSI1

OSI2

OSI3

OSI4

Spare NSO1

NSO2

NSO3

NSO4

OSO1

OSO2

OSO3






OSO4

Features


- Bluetooth connection
- Digital radio
- Cloth seat trim
- Cruise control
- Air conditioning
- Park assist camera
- Front electric windows
- Auxiliary input socket
- Central locking

Photos





Condition Check



Damage Photos

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		