

VEHICLE INSPECTION REPORT

HK73DPY

Mercedes-Benz Atego 816

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Cap Code 999900

Details

Location	Doncaster	GVW	7490kg	Service documents	Printout
Reg. date	23/01/2024	Colour	WHITE	Cab Type	DAY CAB
Year	2024	VIN	W1T96700120690182	Gearbox	AUTOMATIC
Mileage	8,153 Km Warranted	Body Style	Flatbed & Crane	Axle Combi	4x2
Fuel Type	DIESEL	Service history	Yes	Rear Suspension	Steel

WARNING LIGHT ON DASH HIAB X HIDUO 062 B 2 REMOTE CRANE (YEAR 2023)

Tyres


NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4


Features

- Bluetooth connection
- Digital radio
- Cloth seat trim
- Cruise control
- Air conditioning
- Park assist camera
- Front electric windows
- Auxiliary input socket
- Central locking


Photos







Condition Check



Damage Photos



1: Dash Warning Lights
Displayed
No Action

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	-
Engine Runs	OK	No Excessive Smoking	OK

EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	Fault