

VEHICLE INSPECTION REPORT

SK65BLZ

Daf CF 400

Inspection

Serious Damage?	No	VAT	Plus VAT
		V5	Present

Details

Location	Doncaster	GVW	32000kg	Gearbox	MANUAL
Reg. date	22/10/2015	Colour	WHITE	Axle Combi	8x4
Year	2015	VIN	XLRADM4100G059034	Rear Suspension	Steel
Mileage	390,013 Km Warranted	Body Style	Tipper		
Fuel Type	DIESEL	Cab Type	DAY CAB		

BATTERIES MISSING, PALFINGER EPSILON M125L (YEAR 2015), SHEETING SYSTEM

Tyres




NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4
			Punctured	


Features

- Cruise control
- Digital radio
- Air conditioning
- Front electric windows
- Central locking
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips

2: Bumper Front
Rusted
Over 5mm



3: Bumper Front Moulding
Broken
Replace

4: Panel Front
Scratched
Over 25mm Not Thru Paint



5: Door nsf
Scratched
Over 25mm Not Thru Paint

6: Wing nsf
Cracked
Replace



7: Unclassified
Major Parts Missing
Report Only

8: Other
N/A
N/A



9: Door osf
Scratched
Over 25mm Thru Paint

10: Dash Warning Lights
Displayed
No Action



11: Door Pad osf
Broken
Replace

12: Carpets Front
Soiled
Heavy



13: Seat Base Cover osf
Holed
Over 3mm

Interior

Carpet Condition	Poor	Upholstery Condition	Poor
Seat Condition	Poor	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	Fault
ABS light illuminated	OK	DPF light illuminated	Fault