

VEHICLE INSPECTION REPORT

SG66XNJ

Vauxhall Combo 2300 1.6 CDTI 16V 105PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Details

Location	Livingston	GVW	2458kg	CAP Clean	£1,975.00
Reg. date	22/02/2017	Colour	WHITE	CAP Average	£1,675.00
Year	2017	VIN	W0L6WZR1BH9611333	CAP Below	£1,225.00
Mileage	56,405 Miles Warranted	Body Style	Panel Van L2	Gearbox	MANUAL
Fuel Type	DIESEL	MOT Due	16/01/2027	Gears	6

SLIGHT ENGINE RATTLE WHEN FIRST STARTS TWIN SIDE LOAD DOOR, TOW BAR, ROOF RACK.

Tyres

NSF

NSR

OSF


OSR


Spare

Features


- Radio/CD
- Front electric windows
- Central locking

Photos





Condition Check



Damage Photos



1: Sill os
Scratched
Over 25mm Thru Paint

2: Bonnet
Dented
With Paint Damage



3: Wing osf
Dented
With Paint Damage

4: Qtr Panel osr
Dented
With Paint Damage



5: Door nsf
Dented
With Paint Damage

6: Wing nsf
Dented
With Paint Damage

Interior

Carpet Condition	Average		Upholstery Condition	Average
Seat Condition	Average		Odour	No
Engine Runs	OK		Gearbox 1st and Reverse Test	OK
Brakes	OK		Clutch Slip Test from Static	OK
Turbo Boosting	OK		Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK		No Excessive Smoking	OK
EML light illuminated	OK		Oil warning light illuminated	OK
Airbag light illuminated	OK		DPF light illuminated	OK
ABS light illuminated	OK		Service indicator light illuminated	OK

Windows

OK

Radio

OK

Steering

OK