

VEHICLE INSPECTION REPORT

C496807

SDC CURTAINSIDE

Inspection

Vehicle

VAT	Plus VAT
V5	N/A

Details

Location	Doncaster Trailer Centre	Colour	BLUE	Axle Combi	Tri
Reg. date	01/01/2019	VIN	SDCCS45B300168526	Rear Suspension	Air
Year	2019	Body Style	Trailer	Rear Doors	Barn
Mileage	Not Showing	MOT Due	31/08/2027		
Fuel Type		Brakes	Disc		

NEARSIDE CURTAIN TORN, NEARSIDE DOOR HANDLE BROKEN BPW AXLES, RAISE & LOWER VALVE, FERRY LASHING RINGS

Tyres

NSF

NSR

OSF

OSR

Spare

Photos





