

VEHICLE INSPECTION REPORT

FP69YZU

Vauxhall Vivaro 2900 1.5 100PS Edition

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Location	Doncaster	GVW	2830kg	CAP Clean	£6,350.00
Reg. date	31/12/2019	Colour	WHITE	CAP Average	£5,475.00
Year	2019	VIN	VXEVBVYHRKL7006870	CAP Below	£4,275.00
Mileage	66,883 Miles Warranted	Body Style	Panel Van LWB	Gearbox	MANUAL
Fuel Type	DIESEL	MOT Due	16/06/2027	Gears	6

SIDE LOAD DOOR, RACKING, DEADLOCKS, AD-BLUE

Tyres

NSF

NSR

OSF


OSR


Spare

Features

- Bluetooth connection
- Cruise control
- Front parking sensor
- Park assist camera
- Rear parking sensor
- Auxiliary input socket
- Digital radio
- Air conditioning
- Front electric windows
- Drivers airbag
- Passenger airbag
- Central locking
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Panel Front
Chipped
Multiple Chips



3: Bumper Front
Scratched
Over 100mm Thru Paint

4: Wing nsf
Dented
Over 30mm



5: Door nsf
Dented
With Paint Damage

6: Door nsf
Scratched
Over 25mm Thru Paint



7: Door nsf
Scratched
Over 25mm Thru Paint

8: Door nsf
Scratched
Over 25mm Thru Paint



9: Qtr Panel nsr
Scratched
Over 25mm Thru Paint

10: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



11: Qtr Panel nsr
Scratched
Over 25mm Thru Paint

12: Door nsr
Dented
With Paint Damage



13: Door osf
Chipped
Multiple Chips

14: Carpets Front
Holed
Over 3mm



15: Seat Base Cover osf
Soiled
Heavy

Interior

Carpet Condition	Poor	Upholstery Condition	OK
Seat Condition	Poor	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		