

VEHICLE INSPECTION REPORT

BN21ANF

Iveco Daily 35-120

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Location Doncaster

Reg. date 04/03/2021

Year 2021

Mileage 60,822 Miles
Warranted

Fuel Type DIESEL

GVW 3500kg

Colour WHITE

VIN ZCFC3358605386522

Body Style Panel Van MWB

Service history None

MOT Due 03/10/2026

CAP Clean £10,300.00

CAP Average £9,200.00

CAP Below £7,550.00

Gearbox MANUAL

Gears 6

RACKING, DEADLOCKS, MICROWAVE, 110V OUTLETS, FUSEBOX, AIR OUTLETS , WINTON POWER SYSTEM, SIDE LOAD DOOR, AD-BLUE, E/MIRRORS, WB 4100

Tyres

NSF

NSR

OSF

OSR






Spare


Features

- Bluetooth connection
- Digital radio
- Central locking
- Cruise control
- Air conditioning
- Cloth seat trim
- Front parking sensor
- Front electric windows
- Rear parking sensor
- Drivers airbag


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips

2: Panel Front
Scratched
Over 25mm Thru Paint



3: Door nsf
Scratched
Over 25mm Thru Paint

4: Qtr Panel Moulding ns
Scuffed (Unpainted)
Over 100mm



5: Qtr Panel nsr
Dented
Over 30mm

6: Bumper Rear Moulding
Scuffed (Unpainted)
UpTo 100mm



7: Qtr Panel osr
Scratched
Over 25mm Thru Paint

8: Qtr Panel Moulding os
Scuffed (Unpainted)
UpTo 100mm



9: Door Mirror Assy osf
Scuffed (Unpainted)
UpTo 100mm

10: Screen Front
Chipped
Over 10mm



11: Seat Base Cover osf
Holed
Over 3mm

12: Seat Base Cover nsf
Soiled
Heavy

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	Poor	Odour	No
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		