

VEHICLE INSPECTION REPORT

WP70YTG

Fiat Ducato Maxi 35 2.3 MULTIJET 140PS

Inspection

Serious Damage? No

Vehicle

VAT	Plus VAT
V5	To Follow
Cap Id	44846
Cap Code	FIDU233MM4HDTM2 5 L

Details

Location	Doncaster	Colour	WHITE	CAP Average	£7,700.00
Reg. date	27/01/2021	VIN	ZFA25000002R33070	CAP Below	£6,300.00
Year	2021	Body Style	Panel Van MWB	Gearbox	MANUAL
Mileage	41,918 Miles Warranted	Service history	None	Gears	6
Fuel Type	DIESEL	MOT Due	13/05/2027		
GVW	3500kg	CAP Clean	£8,625.00		

RACKING, DEADLOCKS, SIDE LOAD DOOR

Tyres

NSF

NSR

OSF

OSR


Spare


Features

- Bluetooth connection
- Digital radio
- Passenger airbag
- Front parking sensor
- Air conditioning
- Central locking
- Rear parking sensor
- Front electric windows
- Cloth seat trim
- Auxiliary input socket
- Drivers airbag


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Wing nsf
Scratched
Over 25mm Thru Paint



4: Qtr Panel nsr
Dented
Over 30mm



5: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



6: Qtr Panel Moulding ns
Missing
Replace



7: Qtr Panel nsr
Dented
With Paint Damage



8: Qtr Panel osr
Scratched
Over 25mm Thru Paint



9: Qtr Panel osr
 Scratched
 Over 25mm Thru Paint



10: Qtr Panel osr
 Scratched
 Over 25mm Thru Paint



11: Door osf
 Scratched
 Over 25mm Thru Paint



12: Carpets Front
 Holed
 Over 3mm



13: Fascia Panel
 Soiled
 Heavy

Interior

Carpet Condition	Poor	Upholstery Condition	Poor
Seat Condition	OK	Odour	No
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		