

VEHICLE INSPECTION REPORT

FL69XBA

Vauxhall Vivaro 2900 1.5 100PS EDITION

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Location	Doncaster	Colour	WHITE	CAP Average	£6,600.00
Reg. date	31/12/2019	VIN	VXEVBVYHRKLZ014138	CAP Below	£5,175.00
Year	2019	Body Style	Panel Van LWB	Gearbox	MANUAL
Mileage	42,544 Miles Warranted	Service history	None	Gears	6
Fuel Type	DIESEL	MOT Due	18/10/2026		
GVW	2830kg	CAP Clean	£7,650.00		

WARNING LIGHT ON DASH, RACKING, DEADLOCKS (NO KEYS), TWIN SIDE LOAD DOORS

Tyres

NSF

NSR

OSF

OSR




Spare

Features


- Bluetooth connection
- Cruise control
- Front parking sensor
- Park assist camera
- Rear parking sensor
- Auxiliary input socket
- Digital radio
- Air conditioning
- Front electric windows
- Drivers airbag
- Passenger airbag
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips

2: Seat Base Cover nsf
Soiled
Heavy



3: Dash Warning Lights
 Displayed
 No Action

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	Poor	Odour	No
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	Fault	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	Fault