

VEHICLE INSPECTION REPORT

YA17LMM

Iveco Daily 35-140

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Location	Doncaster	VIN	ZCFCD35A20D576288	MOT Due	04/02/2027
Reg. date	11/07/2017	Body Style	Curtainside	CAP Clean	£8,075.00
Year	2017	Service history	Part	CAP Average	£6,725.00
Mileage	37,707 Miles Warranted	Service documents	Service Book	CAP Below	£5,000.00
Fuel Type	DIESEL	Number of stamps	8	Gearbox	MANUAL
GVM	3500kg	Last service date	03/02/2026	Gears	6
Colour	WHITE	Last service miles	35,914		

NSR DOOR INOP 3450 WB, E/MIRRORS

Tyres

NSF

NSR

OSF

OSR




Spare

Features

- Bluetooth connection
- Front electric windows
- Cloth seat trim
- Cruise control
- Drivers airbag
- Digital radio
- Passenger airbag
- Radio/CD
- Central locking


Photos







Condition Check



Damage Photos



1: Flasher Side Repeater os
Broken
Replace

2: Bonnet
Chipped
Multiple Chips



3: Panel Front
Scratched
Over 25mm Thru Paint

4: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm



5: Door nsf
Dented
With Paint Damage

6: Door Moulding osr
Broken
Replace



7: Door osr
Scratched
Over 25mm Thru Paint

8: Door Mirror Glass os
Broken
Replace



9: Door Moulding osf
Scuffed (Unpainted)
Over 100mm

10: Door osf
Dented
With Paint Damage



11: Wing osf
Dented
Over 30% Of Panel

12: Carpets Front
Holed
Over 3mm



13: Seat Base Cover osf
Torn
Over 3mm

14: Seat Base Cover nsf
Soiled
Heavy

Interior

Carpet Condition	Poor	Upholstery Condition	OK
Seat Condition	Poor	Odour	No
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		