

VEHICLE INSPECTION REPORT

HF20SZK

ISUZU N 65.150

Inspection

Vehicle

VAT	Plus VAT
V5	To Follow

Details

Location	Bedford	VIN	JAANPR85KK7100072	Cab Type	DAY CAB
Reg. date	11/08/2020	Body Style	Box Van	Gearbox	MANUAL
Year	2020	Service history	Full	Axle Combi	4x2
Mileage	353,297 Km Not Warranted	Service documents	Service Book	Rear Suspension	Steel
Fuel Type	DIESEL	Last service date	04/06/2026	Rear Doors	Barn
GVW	6500kg	Last service miles	342,774		
Colour	WHITE	MOT Due	31/01/2027		

FAULTY CLUTCH-HIGH BITING POINT

Tyres

NSF

NSR

OSF

OSR

Spare

Photos



