

VEHICLE INSPECTION REPORT

VU10LFA

MERCEDES ATEGO 815

Inspection

Vehicle

VAT	Plus VAT
V5	Present

Details

Reg. date	01/03/2010	Colour	WHITE	Gearbox	MANUAL
Year	2010	VIN	WDB9700212L460738	Axle Combi	4x2
Mileage	183,877 Km Not Warranted	Body Style	Tipper	Rear Suspension	Steel
Fuel Type	Diesel	Cab Type	DAY CAB		

*WARNING LIGHT ON DASH**TIPPER BODY ROTTEN* PENNY HYDRAULIC LIFT CRANE, BROOKSIDE STEEL BODY, EDBRO TIPPING GEAR

Tyres

NSF

NSR

OSF

OSR

Spare

Features

- Park assist camera

Photos





