

VEHICLE INSPECTION REPORT

SJ16XLY

Daf LF 220

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 25/05/2016

Year 2016

Mileage 137,641 Km Not Warranted

Fuel Type Diesel

Colour YELLOW

VIN XLRAEL3700L449069

Body Style Tanker

Keys 1

Gearbox Automatic

Steering Combi Steer

Rear Suspension Steel

Tyres

NSF NSI1

NSI2

NSI3

NSI4

OSF OSI1

OSI2

OSI3

OSI4

Spare NSO1

NSO2

NSO3

NSO4

OSO1

OSO2



OSO3


OSO4

Features


- Radio/CD
- Front electric windows
- Central locking
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Seat Base Cover osf
Torn
Over 3mm



2: Sill os
Rusted
Over 5mm



3: Door Moulding osf
Scuffed (Unpainted)
Over 100mm

4: Bonnet
Scratched
Over 25mm Thru Paint



5: Bumper Front Grill
Broken
Replace

6: Door osf
Dented
Over 30mm



7: Door Moulding osf
Broken
Replace

8: Qtr Panel osr
Rusted
Over 5mm



9: Tailgate
Rusted
Over 5mm

10: Qtr Panel nsr
Rusted
Over 5mm



11: Door nsf
Dented
Over 30mm

Interior

Carpet Condition	Average		Upholstery Condition	Average
Seat Condition	Average		Odour	-
Engine Runs	OK		Gearbox 1st and Reverse Test	OK
Brakes	OK		Clutch Slip Test from Static	OK
Turbo Boosting	OK		Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK		No Excessive Smoking	OK
EML light illuminated	OK		Oil warning light illuminated	OK
Airbag light illuminated	OK		DPF light illuminated	OK
ABS light illuminated	OK		Service indicator light illuminated	OK
Windows	OK		Radio	Fault