

VEHICLE INSPECTION REPORT

CN55MUE

VOLVO B12B PLAXTON PANTHER

Inspection

Vehicle

VAT	Plus VAT
V5	Present

Details

Location	Doncaster	Colour	MULTI-COLOURED	Gearbox	AUTOMATIC
Reg. date	01/01/2006	VIN	YV3R8G1295A102845	Axle Combi	4x2
Year	2006	Body Style	COACH (PLAXTON)	Rear Suspension	Air
Mileage	1,459,397 Km Not Warranted	Service history	None		
Fuel Type	DIESEL	Cab Type	DAY CAB		

WARNING LIGHTS ON DASH, *5% BUYERS FEE* 49 SEATS + DRIVER + CREW, RECLINING FABRIC SEATS WITH FOOTRESTS, 3PT. SEATBELTS, KNEEL FUNCTION, TOILET, REAR EMERGENCY EXIT, FULL WIDTH UNDERBODY STORAGE, OVERHEAD STOWAGE, SCHEDULE 3 PSVAR,

Tyres

NSF
NSR
OSF
OSR
Spare

Features

- Park assist camera
- Digital radio
- Air conditioning

Photos





