

VEHICLE INSPECTION REPORT

MV68XBT

Ford Transit 350 2.0 TDCi 130PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Details

Reg. date 01/09/2018

Year 2018

Mileage 150,048 Miles
Warranted

Fuel Type Diesel

Colour WHITE

VIN WF0XXXTTGXJM55432

Body Style Panel Van L3

MOT Due 09/09/2025

CAP Clean £3,550.00

CAP Average £3,050.00

CAP Below £2,375.00

Gearbox MANUAL

Gears 6

AD-BLUE, SIDE LOAD DOOR

Tyres

NSF

NSR

OSF

OSR



Spare

Features


- Bluetooth connection
- Drivers airbag
- Auxiliary input socket
- Passenger airbag
- Digital radio
- Central locking
- Front electric windows
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Number Plate Front
Broken
Replace



2: Bonnet
Chipped
Multiple Chips



3: Roof
Chipped
Multiple Chips



4: Bumper Front
Scratched
Over 100mm Thru Paint



5: Door Moulding nsf
Scuffed (Unpainted)
Over 100mm



6: Door Moulding nsf
Missing
Replace



7: Qtr Panel nsr
Dented
With Paint Damage



8: Qtr Panel nsr
Dented
Over 30mm




9: Qtr Panel Moulding ns
Scuffed (Unpainted)
Over 100mm




10: Qtr Panel nsr
Dented
Over 30mm



11: Door nsr
Chipped
Multiple Chips



12: Lamp osr
Broken
Replace



13: Qtr Panel osr
Dented
Over 30mm



14:




15: Qtr Panel Moulding os
Scuffed (Unpainted)
Over 100mm



16:



17: Door Pad osf
Soiled
Heavy



18: Seat Base Cover osf
Soiled
Heavy



19: Seat Base Cover nsf
Soiled
Heavy

Interior

Carpet Condition		Upholstery Condition	
Seat Condition		Odour	
OK	Poor	Poor	No
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		