

VEHICLE INSPECTION REPORT

WU66FFX

Man TGM 15.250

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Location Livingston

Reg. date 11/02/2017

Year 2017

Mileage 384,121 Km Not Warranted

Fuel Type DIESEL

GVW 15000kg

Colour WHITE

VIN WMAN16ZZ8HY357210

Body Style Fridge Box

MOT Due 30/09/2026

Cab Type DAY CAB

Gearbox AUTOMATIC

Axle Combi 4x2

Rear Doors Barn

CARRIER SUPRA 1150 MT FRIDGE UNIT, STANDBY PLUG, TWIN SIDE BARN DOORS.

Tyres

NSF

NSR

OSF



OSR





Spare

Features


- Radio/CD

Photos





Condition Check



Damage Photos



1: Seat Base Cover of
Torn
Over 3mm



2: Bonnet
Dented
With Paint Damage




3: Wing osf
Dented
With Paint Damage

4: Bumper Front
Cracked
Over 25mm




5: Door osf
Dented
Over 30mm

6: Door osr
Dented
With Paint Damage



7: Qtr Panel osr
Dented
With Paint Damage

8: Tailgate
Dented
Over 30mm




9: Qtr Panel nsr
Dented
With Paint Damage

10: Door nsr
Dented
With Paint Damage



11: Door nsf
Dented
With Paint Damage

12: Wing nsf
Dented
With Paint Damage



13: Roof
Rusted
Over 5mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No