

# VEHICLE INSPECTION REPORT

**SN18WDM**

## Ford Transit 350 2.0 TDCi 130ps

### Inspection

Serious Damage? No

### Vehicle

VAT Plus VAT

V5 Buyer To Apply

### Details

Reg. date 14/03/2018

Year 2018

Mileage 123,152 Miles  
Warranted

Fuel Type Diesel

Colour WHITE

VIN WF0XXXTTGXHB64844

Body Style Messing Unit

MOT Due Expired

CAP Clean £4,150.00

CAP Average £3,575.00

CAP Below £2,825.00

Gearbox MANUAL

Gears 6

AD-BLUE, SIDE LOAD DOOR, TOW BAR, MICROWAVE, PIPE STORAGE (WITH KEYS)

### Tyres

NSF

NSR

OSF


OSR


Spare

## Features


- Bluetooth connection
- Front electric windows
- Cloth seat trim
- Rear parking sensor
- Drivers airbag
- Auxiliary input socket
- Passenger airbag
- Digital radio
- Central locking

## Photos






## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
Multiple Chips



2: Number Plate Front  
Broken  
Replace



3: Roof  
Chipped  
Multiple Chips



4: Wing nsf  
Scratched  
Over 25mm Thru Paint



5: Qtr Panel Moulding ns  
Scuffed (Unpainted)  
Over 100mm



6: Qtr Panel Moulding ns  
Scuffed (Unpainted)  
Over 100mm



7: Lamp osr  
Broken  
Replace



8: Qtr Panel Moulding os  
Scuffed (Unpainted)  
Over 100mm



9: Qtr Panel Moulding os  
Scuffed (Unpainted)  
Over 100mm



10: Qtr Panel osr  
Dented  
Over 30mm



11: Qtr Panel osr  
Dented  
With Paint Damage



12: Qtr Panel Moulding os  
Scuffed (Unpainted)  
Over 100mm



13: Screen Front  
Chipped  
Over 10mm



14: Door Pad osf  
Soiled  
Heavy



15: Seat Base Cover nsf  
Soiled  
Heavy

16: Door Pad nsf  
Soiled  
Heavy

## Interior

Carpet Condition		Upholstery Condition	
Seat Condition		Odour	
OK		Poor	
Poor		No	
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		