

VEHICLE INSPECTION REPORT

WX70KNA

Fiat Ducato 35 2.3 Multijet I140PS

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	To Follow
		Cap Id	44846
		Cap Code	FIDU233MM4HDTM2 5 L

Details

Location	Doncaster	GVW	3500kg	CAP Clean	£7,625.00
Reg. date	27/01/2021	Colour	WHITE	CAP Average	£6,800.00
Year	2021	VIN	ZFA25000002R34397	CAP Below	£5,575.00
Mileage	63,883 Miles Warranted	Body Style	Panel Van	Gearbox	MANUAL
Fuel Type	DIESEL	MOT Due	21/05/2027	Gears	6


SIDE LOAD DOOR, TOW BAR, E/MIRRORS, AD-BLUE



Tyres	
NSF	
NSR	
OSF	
OSR	
Spare	

Features

- Bluetooth connection
- Digital radio
- Passenger airbag
- Front parking sensor
- Air conditioning
- Central locking
- Rear parking sensor
- Front electric windows
- Cloth seat trim
- Auxiliary input socket
- Drivers airbag


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Wing nsf
Dented
Over 30mm



3: Door nsf
Chipped
Multiple Chips



4: Qtr Panel nsr
Chipped
Multiple Chips



5: Qtr Panel nsr
Scratched
Over 25mm Thru Paint




6: Qtr Panel osr
Scratched
Over 25mm Thru Paint



7: Door osf
Scratched
Over 25mm Thru Paint



8: Carpets Front
Holed
Over 3mm



9: Seat Base Cover osf
Soiled
Heavy



10: Seat Base Cover nsf
Soiled
Heavy



11: Fascia Panel
Scuffed
Over 25mm

Interior

Carpet Condition	Poor		Upholstery Condition	Poor
Seat Condition	Poor		Odour	No
Engine Runs	OK		No Excessive Smoking	OK
EML light illuminated	OK		DPF light illuminated	OK
ABS light illuminated	OK			