

VEHICLE INSPECTION REPORT

KEB519

BEDFORD SA8

Inspection

Vehicle

VAT	Margin
V5	To Follow

Details

Location	Onsite Customer Auction	Fuel Type	DIESEL	Cab Type	DAY CAB
Reg. date	01/01/1959	Colour	RED/BLUE	Axle Combi	4x2
Year		VIN	SLD175066	Rear Suspension	Steel
Mileage	77,663 Miles Not Warranted	Body Style	Tractor Unit		

Leyland 350 Engine, Bedford 2 Sp. Axle, Bedford 4 Sp. Gearbox, Tasker Automatic Coupling

Tyres

NSF
NSR
OSF
OSR
Spare

Photos





