

VEHICLE INSPECTION REPORT

BT18HBZ

Iveco Daily 35-140 2.3 3520WB

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT
V5 Buyer To Apply

Details

Reg. date	30/05/2018	VIN	ZCFCC35A005209077	CAP Below	£3,275.00
Year	2018	Body Style	Panel Van L3	Gearbox	MANUAL
Mileage	101,017 Miles Warranted	MOT Due	Expired	Gears	6
Fuel Type	Diesel	CAP Clean	£4,875.00		
Colour	WHITE	CAP Average	£4,200.00		

WARNING LIGHT ON DASH ON BOARD COMPRESSER & 110V OUTLETS

Tyres

NSF

NSR

OSF


OSR


Spare

Features


- Front electric windows

Photos





Condition Check



Damage Photos



1: Wing osf
Poor Previous Repair
Poor Colour



2: Screen Front
Chipped
UpTo 10mm



3: Bonnet
Chipped
Multiple Chips

4: Front TowEye Cvr
Missing
Replace



5: General Exterior
Soiled
Light

6: Door osr
Dented
Over 30mm



7: Door osr
Rusted
Holed

8: Qtr Panel Arch Extension os
Broken
Replace



9: Bumper Front
Scratched
Over 25mm Not Thru Paint

10: Seat Base Cover osf
Torn
Over 3mm



11: Carpets Front
Holed
Over 3mm

12: Other
N/A
N/A

Interior

Carpet Condition		Average	Upholstery Condition		Average
Seat Condition		Average	Odour		No
Engine Runs	OK		Gearbox 1st and Reverse Test	OK	
Brakes	OK		Clutch Slip Test from Static	OK	
Parking Brake	OK		Gearbox Static Gear Selection (engine running)	OK	
			No Excessive Smoking	OK	
EML light illuminated	Fault		Oil warning light illuminated	OK	
Airbag light illuminated	OK		DPF light illuminated	OK	
ABS light illuminated	OK		Service indicator light illuminated	OK	