

VEHICLE INSPECTION REPORT

YP17AXW

Ford Fiesta 1.5 TDCI

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Details

Reg. date 30/03/2017

Year 2017

Mileage 108,522 Miles
Warranted

Fuel Type Diesel

Colour WHITE

VIN WF0RXXGAKRHM66123

Body Style Car Derived Van

CAP Clean £1,675.00

CAP Average £1,450.00

CAP Below £1,075.00

Gearbox MANUAL

Gears 5

WARNING LIGHTS ON DASH E/MIRRORS

Tyres

NSF

NSR

OSF

OSR

Spare

Features


- Air conditioning
- Front electric windows

Photos





Condition Check



Damage Photos



1: Wing osf
Scratched
Over 25mm Thru Paint



2: Wing nsf
Dented
Over 2 UpTo 10mm



3: Bumper Front
Chipped
Multiple Chips



4: Screen Front
Chipped
UpTo 10mm



5: Other
N/A
N/A

Interior

Carpet Condition	Average		Upholstery Condition	Average
Seat Condition	Average		Odour	No
Engine Runs	OK		Gearbox 1st and Reverse Test	OK
Brakes	OK		Clutch Slip Test from Static	OK
Parking Brake	OK		Gearbox Static Gear Selection (engine running)	OK
			No Excessive Smoking	OK
EML light illuminated	OK		Oil warning light illuminated	OK
Airbag light illuminated	OK		DPF light illuminated	OK
ABS light illuminated	OK		Service indicator light illuminated	Fault