

# VEHICLE INSPECTION REPORT

**BALEGRAB6**

## FLEXUS BALASYSTEM 402-110

### Inspection

### Vehicle

|     |          |
|-----|----------|
| VAT | Plus VAT |
| V5  | N/A      |

### Details

|           |            |           |             |            |           |
|-----------|------------|-----------|-------------|------------|-----------|
| Location  | Livingston | Mileage   | Not Showing | VIN        |           |
| Reg. date |            | Fuel Type |             | Body Style | Bale Grab |
| Year      |            | Colour    |             |            |           |

\*SERIAL PLATE MISSING\*, MANITOU FITTING, 2500KG MAX LOAD.

### Tyres

|       |
|-------|
| NSF   |
| NSR   |
| OSF   |
| OSR   |
| Spare |

### Photos



