

## VEHICLE INSPECTION REPORT

**HL68GNK**

### Ford Transit Connect 1.5 ECOBLUE 75PS

#### Inspection

Serious Damage? No

#### Vehicle

VAT Plus VAT  
V5 Buyer To Apply

#### Details

Reg. date	21/02/2019	VIN	WF0RXXWPGRJA20500	CAP Below	£2,400.00
Year	2019	Body Style	Panel Van L1	Gearbox	MANUAL
Mileage	125,473 Miles Warranted	MOT Due	20/02/2026	Gears	6
Fuel Type	Diesel	CAP Clean	£3,425.00		
Colour	WHITE	CAP Average	£3,000.00		

\*WARNING LIGHT ON DASH, ONLY RUNS WITH JUMP PACK ATTACHED, DASH DOES NOT DISPLAY\* AD BLUE

#### Tyres

NSF

NSR

OSF


OSR

Spare

## Features

- Front electric windows


## Photos







## Condition Check



## Damage Photos



1: Wing of  
Chipped  
Multiple Chips



2: General Exterior  
Soiled  
Light



3: Screen Front  
Chipped  
UpTo 10mm



4: Bonnet  
Chipped  
Multiple Chips



5: Panel Front  
Chipped  
Multiple Chips



6: Bumper Front  
Scratched  
Over 25mm Not Thru Paint



7: Bumper Front  
Scratched  
Over 25mm Not Thru Paint



8: Wing nsf  
Dented  
Over 2 UpTo 10mm



9: Door nsf  
Chipped  
1 To 5



10: Door nsr  
Chipped  
Multiple Chips



11: Qtr Panel nsr  
Chipped  
Multiple Chips



12: Qtr Panel osr  
Dented  
Over 30mm



13: Qtr Panel Trim os  
Scuffed  
Over 25mm



14: Qtr Panel osr  
Chipped  
Multiple Chips





15: Carpets Front  
Holed  
Over 3mm

Interior

Carpets Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No
Engine Runs	Fault		