

VEHICLE INSPECTION REPORT

YH18AUA

Ford Ranger XL 2.2 TDCI 150PS

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Present
		Cap Id	22413
		Cap Code	FORA22XL 7DTM4 4 L

Details

Location	Doncaster	Colour	WHITE	CAP Clean	£4,350.00
Reg. date	30/04/2018	VIN	6FPGXXMJ2GHC17134	CAP Average	£3,650.00
Year	2018	Body Style	Pick-up	CAP Below	£2,700.00
Mileage	153,246 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	DIESEL	Service documents	Printout	Gears	6
GVW	3200kg	MOT Due	01/01/2027		

ONLY RUNS WITH BOOST PACK, OUTSTANDING RECALL ON MOT, ALTERNATOR ISSUES AD-BLUE, TOW BAR, ROOF RACK

Tyres



NSF
NSR
OSF
OSR
Spare

Features

- Bluetooth connection
- Air conditioning
- Central locking
- Park assist camera
- Front electric windows
- Cloth seat trim
- Auxiliary input socket
- Drivers airbag
- Digital radio
- Passenger airbag


Photos







Condition Check



Damage Photos



1: Door Mirror Assy osf
Scuffed (Unpainted)
Over 100mm



2: Door osf
Chipped
Edge Chip



3: Panel Rear
Chipped
Multiple Chips



4: Boot Lid
Rusted
Holed



5: Panel Rear
Chipped
Multiple Chips



6: Panel Rear
Dented
Over 30mm



7: Door nsf
Scratched
Over 25mm Not Thru Paint



8: Wing nsf
Chipped
Over 5mm



9: Wing nsf
Chipped
Over 5mm



10: Wing nsf
Chipped
Over 5mm



11: Wing nsf
Chipped
Over 5mm



12: Carpets Front
Holed
Over 3mm

Interior

Carpet Condition		Average		Upholstery Condition		Average	
Seat Condition		Average		Odour		No	
Engine Runs	OK			Gearbox 1st and Reverse Test	OK		
Brakes	OK			Clutch Slip Test from Static	OK		
Turbo Boosting	OK			Gearbox Static Gear Selection (engine running)	OK		
Parking Brake	OK			No Excessive Smoking	OK		
EML light illuminated	OK			Oil warning light illuminated	OK		
Airbag light illuminated	OK			DPF light illuminated	OK		
ABS light illuminated	Fault			Service indicator light illuminated	OK		
Windows	Fault			Radio	OK		
				Steering	Fault		

