

VEHICLE INSPECTION REPORT

YF66UZC

Ford Transit Custom 290 2.0 TDCI 105PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Location	Bedford	GVW	2940kg	CAP Clean	£2,675.00
Reg. date	01/01/2017	Colour	WHITE	CAP Average	£2,250.00
Year	2017	VIN	WF0YXXTTGYGY77856	CAP Below	£1,650.00
Mileage	128,690 Miles Warranted	Body Style	Panel Van L1	Gearbox	MANUAL
Fuel Type	DIESEL	MOT Due	07/10/2026	Gears	6

WARNING LIGHT ON DASH AD BLUE, SIDE LOADING DOOR, E/MIRRORS

Tyres

NSF

NSR

OSF

OSR


Spare

Features


- Rear parking sensor
- Air conditioning
- Front electric windows

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips

2: Screen Front
Cracked
Replace



3: Roof
Rusted
Over 5mm

4: Front TowEye Cvr
Missing
Replace



5: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm

6: Door nsf
Dented
Between 10mm + 30mm



7: Door nsf
Dented
With Paint Damage

8: Door nsr
Dented
With Paint Damage



9: Door nsr
Dented
Between 10mm + 30mm

10: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



11: Door osr
Dented
With Paint Damage

12: Door osf
Dented
With Paint Damage



13: Seat Base Cover osf
Holed
Over 3mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK