

## VEHICLE INSPECTION REPORT

**CP62NFG**

### Ford Transit Connect 230 TDCi 90ps

#### Inspection

Serious Damage? No

#### Vehicle

VAT Plus VAT

V5 Present

#### Details

Location Avonmouth

Reg. date 23/01/2013

Year 2013

Mileage 186,911 Miles Not Warranted

Fuel Type DIESEL

GVW 2340kg

Colour SILVER

VIN WF0UXXTTPUCS04663

Body Style Panel Van LWB

MOT Due Expired

CAP Clean £720.00

CAP Average £560.00

CAP Below £400.00

Gearbox MANUAL

Gears 5

#### SIDE LOAD DOOR

#### Tyres

NSF

NSR

OSF

OSR


Spare

### Features


- Bluetooth connection
- Front electric windows
- Cloth seat trim
- Rear parking sensor
- Drivers airbag
- Radio/CD
- Passenger airbag
- Air conditioning
- Central locking

### Photos





## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
Multiple Chips

2: Front TowEye Cvr  
Missing  
Replace




3: Bumper Front  
Scratched  
Over 100mm Thru Paint

4: Wing nsf  
Rusted  
Over 5mm



5: Wing nsf  
Dented  
Over 30mm

6: Wing Front Arch Extension ns  
Scratched (Painted)  
Over 25mm Thru Paint



7: A Post ns  
Chipped  
Multiple Chips

8: Sill ns  
Rusted  
Over 5mm



9: Door nsf  
Scratched  
Over 25mm Thru Paint

10: Door nsf  
Dented  
Over 30mm



11: Qtr Panel nsr  
Scratched  
Over 25mm Thru Paint

12: Sill ns  
Hole  
Over 10mm



13: Qtr Panel Arch Extension ns  
Scratched (Painted)  
Over 25mm Thru Paint

14: Qtr Panel nsr  
Scratched  
Over 25mm Thru Paint



15: Qtr Panel osr  
Scratched  
Over 25mm Thru Paint

16: Qtr Panel osr  
Scratched  
Rusted



17: Sill os  
Rusted  
Over 5mm

18: Door osf  
Chipped  
Multiple Chips



19: Bumper Front  
Scratched  
Over 100mm Thru Paint

20: Seat Back Cover osf  
Burn  
Over 3mm



21: Air Vents osf  
Damaged  
Replace

22: Fascia Trim  
Damaged  
Replace



23: Fascia Trim  
Damaged  
Replace

24: Sill Panel Trim os  
Scratched (Painted)  
Over 25mm Thru Paint



25: General Interior  
Soiled  
Light

## Interior

| Carpet Condition      | Average | Upholstery Condition                           | Average |
|-----------------------|---------|------------------------------------------------|---------|
| Seat Condition        | Average | Odour                                          | -       |
| Engine Runs           | OK      | Gearbox 1st and Reverse Test                   | OK      |
| Brakes                | OK      | Gearbox Static Gear Selection (engine running) | OK      |
| Parking Brake         | OK      | No Excessive Smoking                           | OK      |
| EML light illuminated | OK      | DPF light illuminated                          | OK      |
| ABS light illuminated | OK      |                                                |         |